



## **PER ACTIVE**



# PERACETIC ACID WHITENER FOR AUTOMATIC WASHING OF FABRICS

- Whitening action
- With peracetic acid
- Optimised for use with Oxipur system products

Peracetic acid whitener, formulated to work at medium and low temperatures. Recommended for any type of linen and water-hardness. PHOSPHATE AND PERBORATE FREE. EN Test: 1276, 1650, 13697, 13727, 13624, 14348, 14476.

### ? HOW TO USE

To be used with the other products of the Oxipur range, and with Sutter Tech automatic dosing systems.

#### **DILUTION**

To be dosed according to the cycle of washing, water hardness and kind of dirt. Please contact the Sutter Professional technician.

#### A TECHNICAL DATA

ASPECT: Clear liquid COLOR: Colorless PERFUME: Technical

PH	Active substance [%]	Density (g/ml)	Pressure (bar)	Viscosity (cP)	Total dry residue [%]
< 1,0	25 ± 1	1.12			







#### **PER ACTIVE**

#### (!) WARNINGS

May intensify fire; oxidiser. Harmful if swallowed. Causes severe skin burns and eye damage. May cause respiratory irritation. Very toxic to aquatic life with long lasting effects. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Store away from combustible materials. Wear eye protection. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water/ shower. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician. In case of fire, use a dry powder fire extinguisher to extinguish. Dispose of contents/container in accordance with applicable regulations. Contents: PERACETIC ACID, HYDROGEN PEROXIDE, ACETIC ACID.





DANGER





WARNING

WARNING

WARNING

#### NOTES

Do not use on wool or nylon. Only for professional use. Safety data sheet available on request.

## **PACKAGING**

 Code	Size	Quantity	Pallet
5383	Kg 22	1	13x2=26

