

# STRAIK N.R.



#### SUPER RINSE-FREE WAX STRIPPER

- Excellent solubilising power for quick removal of wax layers
- No rinse needed
- Any residue does not stop wax adhering to floor

Rinse-free wax stripper with high solubilising power for quick removal of layers of metal cross-linked acrylic wax.

### ? HOW TO USE

Dilute the product in the single disc machine tank to the recommended concentration. Apply the solution directly to the floor using the single disc machine and use the green or black abrasive disc (depending on the floor). Carefully wet vacuum and leave to dry. Remove any streaks or water marks with a damp mop.





## **DILUTION**

10 % (1 L in 10 L of water) For dry wax stripping (50% 1:1 with water).

## **A TECHNICAL DATA**

**ASPECT:** Clear liquid **COLOR:** Colorless/yellow

**PERFUME:** Citrus

**COV:** 0,12%

PH	Active substance [%]	Density (g/ml)	Pressure (bar)	Viscosity (cP)	Total dry residue [%]
> 13 ()	30 + 2	1076			







#### STRAIK N.R.

#### (!) WARNINGS

Causes severe skin burns and eye damage. May cause respiratory irritation. Wear eye protection. IF SWALLOWED: rinse mouth. Do NOT induce vomiting. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. IF IF INHALED: Remove person to fresh air and keep comfortable for breathing. IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician. Contents SODIUM METASILICATE PENTAHYDRATE, SODIUM HYDROXIDE, 2-AMINOETHANOL.





DANGER

## NOTES

Do not use on linoleum. Sutter Professional cannot be considered liable for any damage due to improper product use.

Only for professional use. Safety data sheet available on request.

# **PACKAGING**

_	Code	Size	Quantity	Pallet
	3820	Kg 5	4	9x4=36

